
SITE PROGRESS I SAFETY & SECURITY-SITE PROGRESS IMAGE





YARD HYDRANT ERECTION - SOUTH WEST SIDE



SPRINKLER FINAL PAINTING – TEMPLE FLOOR

SITE PROGRESS I PHE-SITE PROGRESS IMAGE




SOIL LINE LINE-WEST SIDE




STROM WATER LINE- NORTH EAST SIDE

SITE PROGRESS I INTERNAL ELECTRICAL WORK-SITE PROGRESS IMAGE



CABLE TRAY WORK- TEMPLE FLOOR NT WING




LIGHTING WIRING – TEMPLE FLOOR NT WING

SITE PROGRESS I INTERNAL ELECTRICAL WORK-SITE PROGRESS IMAGE



CEILING WIRING WORK- NT WING



CABLE TRAY WORK- NT WING


SITE PROGRESS I HVAC WORK – SITE PROGRESS IMAGES





DUCTING – TEMPLE FLOOR

SITE PROGRESS I ACCESS & CCTV WORK – SITE PROGRESS IMAGES





WALL CONDUIT FOR READER–M3 FLOOR



ACCESS CONDUIT – UTILITY FLOOR

SITE PROGRESS I AV WORK – SITE PROGRESS IMAGES





AV CONDUITING-TEMPLE FLOOR


SITE PROGRESS I PUJARI FLOOR PHOTOGRAPHS-CIVIL & INTERIOR WORKS



FESTIVAL KITCHEN-SNAG RECTIFICATION IN PROGRESS




SITE PROGRESS I UTILITY FLOOR PHOTOGRAPHS-CIVIL & INTERIOR WORKS




TOILET A-WINDOW FIXING IN PROGRESS



Coffered Ceiling Progress Pictures



SS Sub-frame erection



Centre Diamond frames & Main subframes fit-up work

Coffered Ceiling Progress Pictures




Temp Structure Platform

SS Sub-frames erection

Coffered Ceiling Progress Pictures





Level Marking

SS Sub-frames erection

Coffered ceiling Fabrication Shop



FIT UP WELDING



SITE PROGRESS I SIDE DOME MT WING - COFFERED CEILING WORKS

SAFETY NET LOAD TESTING





TEMPORARY STRUCTURE MOCK UP



